

Femoral fracture following knee ligament reconstruction surgery due to an unpredictable complication of bioabsorbable screw fixation: a case report and review of literature

Sujith Konan · Fares Sami Haddad

Received: 24 May 2009 / Accepted: 17 November 2009 / Published online: 17 December 2009
© Springer-Verlag 2009

Abstract We report an unusual case of femoral fracture from minimal trauma, due to the rapid disappearance of a bioabsorbable interference screw used for reconstruction of the posterolateral corner of the knee. The literature on bone tunnel fractures following knee ligament reconstruction surgery is also reviewed.

Keywords Bone tunnel fracture · Bioabsorbable screws · Ligament reconstruction · Adverse effects

Introduction

Interference screws used for knee ligament reconstructive surgery are a popular application of bioabsorbable materials in orthopedics. They offer various advantages [1, 2] over traditional metallic implants, such as the ability to engineer them to provide an optimum degradation profile, a reduced need for implant removal, and less distortion on magnetic resonance imaging (MRI).

Poly lactide carbonate (PLC) is a combination of an amorphous bioabsorbable polymer, poly DL-lactide-co-glycolide (PDLG), with calcium carbonate, a bone-stimulating material and neutralizing agent [3]. PLC was used to develop the “Calaxo” (Smith & Nephew, Andover, MA, USA) interference screw for knee ligament reconstruction surgery.

Case report

Consent was obtained from the patient to publish his case. A 26-year-old man underwent arthroscopic reconstruction of his anterior cruciate ligament (ACL), posterior cruciate ligament (PCL) and posterolateral corner following a multiple-ligament knee injury obtained while playing rugby. The patient had undergone a twisting knee injury during a tackle and was immediately diagnosed as having a severe knee injury and referred to the senior author (FSH). An MRI scan performed within twenty-four hours of the injury confirmed a tear of the ACL, PCL and posterolateral corner.

Surgical technique of ligament reconstruction

For ACL reconstruction, two semitendinosus allografts were used to fashion a four-strand 10 mm-thick graft which was fixed with an endoloop (Smith & Nephew) on the femoral side and a 9 mm by 25 mm PLC (Calaxo, Smith & Nephew) interference screw on the tibial side. For the PCL reconstruction, an Achilles tendon allograft was fixed to the femoral side by a 9 mm by 25 mm PLC (Calaxo, Smith & Nephew) screw and to the tibial side by a 9 mm by 35 mm PLLA (RCI, Smith & Nephew) screw. For the reconstruction of the posterolateral corner of the knee, two semitendinosus allografts were passed: one into an anterior-to-posterior through-and-through hole in the fibula, and the other through an anteroposterior tunnel in the tibia adjacent to the fibula. The tibial end of the graft was fixed with an 8 mm by 25 mm PLC (Calaxo, Smith & Nephew). The two free ends of the fibular allograft and one free end of the tibial allograft were then passed subfascially and fixed into a 9 mm tunnel drilled at an isometric point above the lateral epicondyle of the femur. The allograft was then fixed in the femoral tunnel

S. Konan (✉) · F. S. Haddad
Department of Trauma and Orthopaedics,
University College Hospital, London WC1E 5DB, UK
e-mail: docsujith@yahoo.co.uk

Fig. 1 Immediate postoperative plain radiographs with illustration of tunnel positions on the lateral femoral condyle illustrated on the AP view. The lateral tunnel is placed in a more anterior plane in relation to the ACL tunnel



using a 10 mm by 35 mm PLC (Calaxo, Smith & Nephew) screw. An image intensifier was used to guide the positioning of each screw. Meticulous care was taken to ensure that, when bone tunnels were adjacent, they were placed such that no compromise to bone strength would occur (see postoperative radiographs—Fig. 1). Excellent knee stability was noted on the table.

Postoperatively the patient was mobilized nonweight-bearing for 2 months in a knee brace, and specialist physiotherapy was initiated for muscle strengthening and range of movements. After 2 months he was allowed to weight-bear. His brace was removed after 16 weeks.



Fig. 2 CT image of the fracture in the femoral tunnel. Note the absence of the bioabsorbable screw

The immediate postoperative recovery was unremarkable and the patient made satisfactory progress with regards to rehabilitation. Six months after the procedure, the patient presented with sudden onset of knee pain after minor trauma that involved slipping but not falling in a changing room. There was no preceding trauma. On a computed tomography scan (CT—Fig. 2), the femoral fixation screw [10 mm by 35 mm PLC (Calaxo, Smith & Nephew)] of the posterolateral corner allograft was found to be completely degraded, and a minimally displaced fracture was noted through the tunnel (Fig. 3). No bone regeneration was noted in the tunnel. As knee stability was not compromised, the patient was managed conservatively by immobilization in a brace for six weeks. The recovery was satisfactory, with a return to pre-morbid function by approximately 14 months after surgery (see weight-bearing radiographs—Fig. 4). At 24 months of follow-up, the patient continues to have very good functional results, with bilaterally equal range of movements in the knee. Clinical examination using Lachman's test, the drawer test and the collateral stress test have confirmed a stable knee joint.

Discussion

The main disadvantages associated with the use of bioabsorbable implants are their comparatively low mechanical strength, their relatively high cost, and the undesirable biological response [1] they may produce. The persistence of bioabsorbable screws for up to 3 years after their insertion is well documented in MRI studies after knee ligament reconstruction surgery [4–6].

In ovine models [3], the PLC screws have shown gradual and controlled degradation, stimulating ossification of the graft within the bone tunnel. New bone thus formed

Fig. 3 Plain radiographs showing the minimally displaced fracture. Please note the “empty tunnels” on the rotation views



Fig. 4 Plain radiographs taken at 14 months suggest a healed fracture

was noted around the margin of the screw as early as 6–12 weeks. This was followed by partial integration of the screw with bone by 26 weeks and complete replacement with new bone at 52 weeks. Computed tomography data followed this pattern, with extensive integration of the screw to bone by 26 weeks and disappearance of the screw by 52 weeks. An interference screw that would replenish the bone tunnel would be an ideal choice for knee ligament reconstruction surgery. However, clinical studies looking at the outcome of PLC screws are lacking.

There are few reports of femoral fractures at the sites of graft fixation associated with ACL reconstruction

(Table 1). Noah et al. [7] in 1992 and Radler et al. [8] in 2000 reported an extracondylar femur fracture at the site of extra-articular augmentation of ACL reconstruction. In the former case, the fracture occurred 6 months after an ilio-tibial band augmentation of a patellar tendon graft ACL reconstruction, whereas the latter case followed 20 months after the removal of a lateral augmentation device used in an ACL reinsertion.

In the case reported by Manketelov et al. [9] in 1998, the fracture extended from the staple of the extra-articular augmentation to the intraosseous tunnel, 24 months after a hamstring autograft ACL reconstruction with extra-

Table 1 Femur fracture

Author	Procedure	Fixation	Time from procedure
Noah et al. [7]	Patellar tendon ACL reconstruction and ITB extra-articular tenodesis	Interference screw	6 months
Ternes et al. [10]	GORE-TEX graft ACL revision	N/A	8 weeks
Wiener and Siliski [11]	Patellar tendon ACL revision		7 months
Manktelow et al. [9]	Hamstring tendon ACL reconstruction with extra-articular tenodesis		24 months fracture from staple of extra-articular augmentation to intraosseous tunnel
Berg et al. [13]	BPTB ACL reconstruction		8 weeks
Radler et al. [8]	ACL reinsertion and LAD. Latter removed after 5 months	6.5 mm cancellous screw	20 months
Mithoefer et al. [14]	Patellar tendon ACL reconstruction	7 × 25 metal interference screw for a 10 mm tunnel	5 months. Fall and hyperextension injury
Wilson et al. [15]	BPTB ACL reconstruction	Interference screw, ? size	9 months, fall
Sheps et al. [12]	Quadrupled ST-G autograft ACL reconstruction	Endoloop button	5 months, head injury, ? fall

Table 2 Tibial plateau fracture

Author	Procedure	Fixation	Time
El-Hage et al. [16]	Achilles tendon ACL reconstruction	Richards interference screw	18 months post-trauma
Morgan and Steensen [17]	ACL reconstruction		
Delcogliano et al. [18]	Patellar tendon ACL reconstruction	10 mm tibial tunnel and 9 × 25 interference screws	7 months
Mithofer et al. [19]	BPTB ACL reconstruction	Post and washer	7 months. Fall down stairs and twisting knee injury
Sundaram et al. [20]	ACL reconstruction	8 mm tunnel fixed with 9 × 25 RCI screws	12 months, fall
Thaunat et al. [21]	ACL reconstruction	11 mm tunnel, 9 mm PGA-co-TMC screw	4 years, valgus compression injury after fall

articular tenodesis. In a case reported by Ternes et al. [10] in 1993, the femoral tunnel used for the placement of a GORE-TEX prosthetic graft was the site of the fracture, which occurred 8 weeks following the procedure. Multiple anterolateral femoral cortex perforations were reported as the etiology for the fracture reported 7 months following a patellar tendon ACL reconstruction by Weiner et al. [11] in 1996, and 5 months following quadrupled hamstring graft ACL reconstruction by Sheps et al. [12] in 2006. Berg et al. [13] in 1999 reported a fracture through the femoral tunnel 8 weeks after a bone—patellar tendon—bone ACL reconstruction. At the time of the operation, the femoral tunnel had been over-drilled and the cortex had been perforated. The femoral tunnel was itself noted to be the stress riser, precipitating a fracture 5 months following patellar tendon ACL reconstruction by Mithoefer et al. [14] in 2005, and 9 months following a similar procedure by Wilson et al. [15] in the same year.

Cases of tibial plateau fracture through the distal fixation site of the ACL grafts have also been reported [16–21] (Table 2). In the case reported by Thaunat et al. [21] in 2006, a 9 mm bioabsorbable screw (polyglycolide-co-trimethylenecarbonate, Endofix, Mansfield, MA, USA) was used to fix the tibial end of a bone patellar tendon bone ACL reconstruction. Four years later the patient presented with tibial plateau fracture following a valgus compression trauma to his knee. Imaging demonstrated screw resorption and tunnel enlargement.

Biomechanical studies have shown that a bone defect such as a screw hole can concentrate stress and decrease the bone strength to torsional loading [22–24]. This may explain the fractures noted in the osseous tunnels following knee ligament reconstruction surgery.

Both mechanical and biological factors have been recognized to contribute to tunnel enlargement after ACL reconstruction [25]. Mechanical factors include motion of

the graft within the tunnel, fixation methods/devices, stress shielding of the graft, improper graft placement, and accelerated rehabilitation. Graft swelling, the use of allograft tissue, synovial fluid propagation within bony tunnels, and increased cytokine levels within the knee are all biologic modes of osteolysis contributing to tunnel enlargement. In most cases tunnel enlargement is minimal after 3 months [25]. Unpredictable bioabsorbable screw resorption results in graft in empty tunnel and perhaps synovial reaction and cytokines, all contributing to persistent tunnel enlargement and bone weakening.

In our case, rapid degradation of the PLC screws in the osseous tunnel in the absence of any attempted bone integration may have predisposed to the fracture by a similar mechanism. Ongoing clinical concerns with the unpredictable absorption of the PLC screws (Calaxo, Smith & Nephew) lead to their withdrawal from the market in 2007. It is crucial to be aware of adverse effects where this particular interference screw has been used.

In conclusion, stress risers may occur following the use of bioabsorbable screws for ligament reconstruction surgery, particularly if screw resorption is rapid and bone integration is not complete.

Femoral fracture presenting as a late complication following the use of bioabsorbable interference screws in knee ligament reconstruction surgery is rare. It is important to be aware of this potential postoperative complication when considering which form of screw fixation to use.

Conflict of interest statement No conflicts of interests or disclosures.

References

- Südkamp NP, Kääb MJ (2002) Biodegradable implants in soft tissue refixation: experimental evaluation, clinical experience, and future needs. *Injury* 33(Suppl 2):B17–B24
- Ambrose CG, Clanton TO (2004) Bioabsorbable implants: review of clinical experience in orthopedic surgery. *Ann Biomed Eng* 32(1):171–177
- Walsh WR, Cotton NJ, Stephens P, Brunelle JE, Langdown A, Auld J, Vizesi F, Bruce W (2007) Comparison of poly-L-lactide and polylactide carbonate interference screws in an ovine anterior cruciate ligament reconstruction model. *Arthroscopy* 23(7):757–765.e1–2
- Drogset JO, Grøntvedt T, Myhr G (2006) Magnetic resonance imaging analysis of bioabsorbable interference screws used for fixation of bone–patellar tendon–bone autografts in endoscopic reconstruction of the anterior cruciate ligament. *Am J Sports Med* 34(7):1164–1169
- Gawęda K, Walawski J, Węglowski R, Krzyżanowski W (2009) Comparison of bioabsorbable interference screws and posts for distal fixation in anterior cruciate ligament reconstruction. *Int Orthop* 33(1):123–7
- Fink C, Benedetto KP, Hackl W, Hoser C, Freund MC, Rieger M (2000) Bioabsorbable polyglyconate interference screw fixation in anterior cruciate ligament reconstruction: a prospective computed tomography-controlled study. *Arthroscopy* 16(5):491–498
- Noah J, Sherman OH, Roberts C (1992) Fracture of the supracondylar femur after anterior cruciate ligament reconstruction using patellar tendon and iliotibial band tenodesis. A case report. *Am J Sports Med* 20:615–618
- Radler C, Wozasek GE, Seitz H, Vecsei V (2000) Distal femoral fracture through the screw hole of a ligament augmentation device fixation. *Arthroscopy* 16:737–739
- Manktelow AR, Haddad FS, Goddard NJ (1998) Late lateral femoral condyle fracture after anterior cruciate ligament reconstruction: a case report. *Am J Sports Med* 26:587–590
- Ternes JP, Blasier RB, Alexander AH (1993) Fracture of the femur after anterior cruciate ligament reconstruction with a Gore-Tex prosthetic graft. A case report. *Am J Sports Med* 21:147–149
- Wiener DF, Siliski JM (1996) Distal femoral shaft fracture: a complication of endoscopic anterior cruciate ligament reconstruction: a case report. *Am J Sports Med* 24:244–247
- Sheps DM, Reed JG, Hildebrand KA, Hiemstra LA (2006) Supracondylar femur fracture after endoscopic anterior cruciate reconstruction using an Endobutton. *Clin J Sport Med* 16:428–429
- Berg EE (1994) Lateral femoral condyle fracture after endoscopic anterior cruciate ligament reconstruction. *Arthroscopy* 10:693–695
- Mithofer K, Gill TJ, Vrahas MS (2005) Supracondylar femoral fracture after arthroscopic reconstruction of the anterior cruciate ligament. *J Bone Joint Surg* 87(7):1591–1596
- Wilson TC, Rosenblum WJ, Johnson DL (2004) Fracture of the femoral tunnel after an anterior cruciate ligament reconstruction. *Arthroscopy* 20:e45–e47
- El-Hage ZM, Mohammed A, Griffiths D, Richardson JB (1998) Tibial plateau fracture following allograft (ACL) reconstruction. *Injury* 29(1):73–74
- Morgan E, Steensen RN (1998) Traumatic proximal tibial fracture following anterior cruciate ligament reconstruction. *Am J Knee Surg* 11(3):193–194
- Delcogliano A, Chiossi S, Caporaso A, Franzese S, Menghi A (2001) Tibial plateau fracture after arthroscopic anterior cruciate ligament reconstruction. *Arthroscopy* 17(4):E16
- Mithofer K, Gill TJ, Vrahas MS (2004) Tibial plateau fracture following anterior cruciate ligament reconstruction. *Knee Surg Sports Traumatol Arthrosc* 12(4):325–328
- Sundaram RO, Cohen D, Barton-Hanson N (2006) Tibial plateau fracture following gracilis-semitendinosus anterior cruciate ligament reconstruction: the tibial tunnel stress-riser. *Knee* 13:238–240
- Thaunat M, Nourissat G, Gaudin P, Beaufile P (2006) Tibial plateau fracture after anterior cruciate ligament reconstruction: role of the interference screw resorption in the stress riser effect. *Knee* 13:241–243
- Burstein AH, Currey J, Frankel VH et al (1972) Bone strength: the effect of screw holes. *J Bone Joint Surg Am* 54:1143–1156
- Brooks DB, Burstein AH, Frankel VH (1970) The biomechanics of torsional fractures: the stress concentration effect of a drill hole. *J Bone Joint Surg Am* 52:507–514
- Juliano PJ, Yu JR, Schneider DJ, Jacobs CR (1997) Evaluation of fracture predilection in the calcaneus after external fixator pin removal. *J Orthop Trauma* 11:430–434
- Wilson TC, Kantaras A, Atay A, Johnson DL (2004) Tunnel enlargement after anterior cruciate ligament surgery. *Am J Sports Med* 32(2):543–548